



Machines II

NoteBook

Dr. Mohammad Z Khader

By: Asma' Hakouz

بأفكارنا نبدع

1st Exam Material

Lecture #1

in a generator:

$\rightarrow e_{ind} = Blv$ for a rotating machine, where r : radius of rotation.

$e_{turn} = 2Blwr \dots \textcircled{1}$

in a motor: (each turn consists of 2 wires.)

$\rightarrow F = Bli$



$T_{turn} = 2Fr = 2Bli r \dots \textcircled{2}$

from ① & ②:


$e_t i = T_t \omega$

$P = T_t \omega$

$T_t = \frac{P}{\omega}$




* a linear machine depends on linear motion.




$\phi = \frac{F}{R} = \frac{Ni}{\left(\frac{l}{\mu A}\right)}$

$\mu = \mu_r \mu_0, \mu_r \approx 10^3$



θ_m depends on the # of slots while Electrical depends on the # of poles.

$\frac{P}{p} = 180^\circ$ electrical degrees (always)
angle between poles = $\frac{360^\circ}{P}$ mechanical degrees.



* refer to appendix B. $p/2$

1) pitch factor $k_p = \sin\left(\frac{\theta_m P}{2}\right)$


P : number of pair of poles.

θ_m : mechanical angle between slots.

$k_{pv} = \sin(v \theta_m P / 2), v = \frac{\theta_m P}{2}$

pitch factor of the v th harmonic.

since harmonics existence distorts the emf, \therefore they must be reduced.
 One method to do this is by reducing the pitch factor for the 3rd, 5th, 7th, ... harmonics;




e.g: $P = 150^\circ$, $150 \times 5 = 750 \equiv 30^\circ \rightarrow k_p = 0.259$

$150 \times 3 = 450 \equiv 90^\circ \rightarrow k_p = 0.7071$

Fundamental: $150 \times 1 = 150 \rightarrow k_p = 0.9659$

Lecture #2



$$K_p = \sin\left(\frac{\theta_m p}{2}\right)$$

eg:- 2-pole stator has coils with $\frac{5}{6}$ pitch, find K_p ?

$$p = \frac{5}{6} \times 180^\circ = 150^\circ$$

$p = 1$ pair of poles.

$$K_p = \sin\left(\frac{150}{2}\right) = 0.96$$

* let # of slots = 64 \Rightarrow 360° mechanical
 & # of poles = 4 & 2x360° electrical
 180° electrical = $\frac{64}{4} = 16$ slots.

→ reduction by 1: 15 slots

$$K_p = \sin\left(\frac{180}{2} \times \frac{15}{16}\right) = 0.995$$

for the v^{th} harmonic:

$$K_{pv} = \sin\left(\frac{p v \theta}{2}\right)$$

electrical degrees.

mechanical

for the 3rd harmonic: $K_{p3} = \sin\left(\frac{180}{2} \times \frac{15}{16} \times 3\right) = 0.956$


→ reduction by 2: 14 slots

$$K_{p3} = \sin\left(\frac{180}{2} \times \frac{14}{16} \times 3\right) = 0.83$$

you can keep reducing # of slots until you get rid of the harmonics.

	K_p	\rightarrow 120/180	\leftarrow
1 st	0.96	0.866	
3 rd	0.83	0	\leftarrow reduced to $\frac{1}{3}$
5 th	0.5	;	so it's been canceled.

2) Distribution factor:



e.g. 30 slots.

* of poles = 2

→ distribution factor $k_d = \frac{\text{actual sum of voltages (Phasor Sum)}}{\text{\# of slots} \times \text{emf of one slot}}$

$$= \frac{\sin\left(\frac{n\delta}{2}\right)}{n \sin\left(\frac{\delta}{2}\right)}$$

$$k_{dv} = \frac{\sin\left(\frac{n\delta v}{2}\right)}{n \sin\left(\frac{\delta v}{2}\right)}$$

δ : angle between two consecutive slots

in this ex: $n = 5$ ($\frac{\text{\# of slots / phase}}{2}$)

$$\delta = \frac{360}{30} = 12^\circ$$

$$\therefore k_d = \frac{\sin\left(\frac{12^\circ \times 5}{2}\right)}{5 \sin\left(\frac{12^\circ}{2}\right)} = 0.957$$

- * the induced emf will be reduced by a factor of k_d & k_p
- * harmonics magnitude decreases as n increases, except for tooth harmonics, which have high magnitude.

* Tooth harmonics at

$$\frac{2MS \mp 1}{P}$$

P : # of poles

S : # of slots

M : integer = 1, 2, 3, ...

for the previous ex.

$$p=2, S=30$$

\therefore tooth harmonics are: 29, 31 & 59, 61 & 89, 91 & ...

for $M=1$

for $M=2$

for $M=3$...


3) Skew factor:

if the slot is parallel to the axis $k_{skew} = 1$

\Rightarrow Winding factor

$$k_w = k_p k_d k_s$$

• Flux in 3-phase windings:



$$i_A = I_m \sin(\omega t)^{-0^\circ} \quad / 0^\circ$$

$$i_B = I_m \sin(\omega t - 120^\circ) \quad / 120^\circ$$

$$i_C = I_m \sin(\omega t - 240^\circ) \quad / 240^\circ$$

↑
time-wise

Space-wise shift.

$$B = \mu H$$

$$= \frac{\mu NI}{l}$$

$$B_{total} = \vec{B}_A + \vec{B}_B + \vec{B}_C$$

$$= B_m \sin(\omega t) / 0^\circ + B_m \sin(\omega t - 120^\circ) / 120^\circ + B_m \sin(\omega t - 240^\circ) / 240^\circ$$

$$= B_m \sin(\omega t) \vec{x} - [0.5 B_m \sin(\omega t - 240^\circ) \vec{x}] + \left[\frac{\sqrt{3}}{2} B_m \sin(\omega t - 240^\circ) \vec{y} \right]$$

$$- [0.5 B_m \sin(\omega t - 120^\circ) \vec{x}] - \left[\frac{\sqrt{3}}{2} B_m \sin(\omega t - 120^\circ) \vec{y} \right]$$

$$= 1.5 B_m \sin(\omega t) \vec{x} + 1.5 B_m \cos(\omega t) \vec{y}$$

Lecture #3

$$e_{ind} = Blv$$

$$F = Bli \rightarrow i(\vec{l} \times \vec{B})$$

$$\vec{T}_{ind} = Fr \sin \theta$$

$$\vec{T}_{turn} = 2r(Bli) \sin \alpha \rightarrow \text{between } l \text{ \& } B$$

$$= k(B_{loop} \times B_{stator}) = k(B_{rotor} \times B_s) \dots \textcircled{1}$$

→ this includes reduction due to pitch, distribution & skew factors.

* direction of rotation is determined from the direction of both l & B .

$$\vec{B}_{net} = \vec{B}_R + \vec{B}_s$$


$$\therefore \vec{B}_R = \vec{B}_{net} - \vec{B}_s$$

plug into $\textcircled{1}$

$$\vec{T} = k [\vec{B}_{net} \times \vec{B}_R - \vec{B}_s \times \vec{B}_s]$$

$$= k \vec{B}_{net} \times \vec{B}_R = \textcircled{D} \angle \delta : \text{angle between } B_R \text{ \& } B_{net}.$$

$$= k B_{net} B_R \sin(\delta)$$




$$\eta = \frac{P_{out}}{P_{in}} \times 100\%$$

for both gen. & motor.

$$P_{in} = T_{app} \omega_m$$

$$P_{out} = \sqrt{3} V_L I_L \cos \theta$$

generator.




$$P_{in} = \sqrt{3} V_L I_L \cos \theta$$

$$P_{out} = T_{load} \times \omega_m$$


motor

due to approximations in equivalent CKTs, sbt variation of the flux, & spaces between laminations which contains a (not 100% insulator), - also all models of a machine assumes infinite length which isn't true.




• Synchronous generators:

- * Salient pole.
- * Cylindrical pole.



AC needs 3 \rightarrow Δ or Y without neutral
or
6 \rightarrow general
or
4 \rightarrow star with neutral.
 \downarrow
wires, brushes, ...

* for motor we give both a.c. & d.c.
in generator we give d.c. & get a.c.




$$n_s = \frac{120f}{P}$$

synchronous speed.


$p \uparrow$ $n_s \downarrow$
friction, windage, ... \downarrow

Salient rotor.


for 4 poles, it rotates 180° mechanical degrees to produce 360° electrical degrees.



• cylindrical
rotor:



→ waveform is closer to a sine wave since the change is gradual ($\frac{d\psi}{dt}$)



** to connect two generators in parallel they must have:


1. the same phase sequence
2. the same voltage.
3. the same frequency.
4. phase shift = 0

* infinite bus bar \equiv constant $V \& f$.

* dynamic reserve: \uparrow ^{extra} generators that work online, in case a generator has stopped another will step in to supply the load.

Lecture #4

Synchronous Generators:



$$E_f = V_T + I_a Z_s$$

↑ induced emf

$$Z_s = R_a + jX_s$$

$$X_s = X_l + X_{ar}$$

↑ synch. reactance ↑ leakage ↑ armature reaction


- * no current → leakage reactance only.
- * current flow will produce armature reaction.

* in dc machines, armature reaction was subtracted algebraically since it's parallel to the current (in the opposite direction).


* in ac machines, armature reaction is ⊥ current which produces the flux, ∴ it's equivalent to a reactance.

* we can't measure X_s directly, therefore we conduct two tests:


- no-load (open CKT) test.
- SC test.





open CKT test.
Characteristics.
(at full load).




$$\frac{E_{f \text{ rated}}}{I_{sc \text{ rated}}} = Z_s \text{ at rated}$$






usually $R_a \ll X_s$
 $\therefore I_L \approx I_x$

→ neglecting R to study the performance of the machine is accepted
* but in efficiency calculations, R is important.



$P = 3V_T I_L \cos \theta = \frac{3V_T E_f \sin \delta}{X_s} \quad P \rightarrow \delta$




$T = k (\vec{B}_{aet} \times \vec{B}_r)$
 $T = k B_{aet} B_r \sin(\delta)$


if the load is small, B_r will come closer to B_p

this is for a gen. with $\eta = 100\%$.

① To maintain constant power:



② to maintain constant $|I_f|$ while p varies:




$$P = \frac{3V_T E_f \sin \delta}{X_s}$$


const.

V_T assumed constant; infinite bus bar

$$I_L = \frac{E_f - V_T}{jX_s} \quad \text{this equation is true in mag. \& direction.}$$


③ to maintain constant p.f.






Limitations:-

1. Power limit (Prime mover's limit).



rotate by 90°
then flip.



** Solve Chapter 4 Problems.

ex: 2300V } max I $\rightarrow \frac{1000000}{\sqrt{3} \times 0.8 \times 2300} = \boxed{313.7A}$

1000KVA

0.8 p.f

2P

Y

$$P_{\text{Stator}} = 3 \times 313.7^2 \times 0.15$$

$$= \boxed{44305W}$$

Stator copper loss

$$X_s = 1.1 \Omega$$

$$I_F = 10A, \text{ from B-H curve} \rightarrow E_f = 2920V \text{ (L-L)}$$

$$R_a = 0.15 \Omega$$

$$Q = \frac{-3V_T^2}{X_s} = \frac{-3 \times (2300)^2}{1.1} = 4809 \text{ KVAR}$$

center

$$P_{\text{WBF}} = 24 \text{ KW}$$

$$P_{\text{Pct}} = 18 \text{ KW}$$

Rotor
copper
losses.


$$\text{radius} = \frac{3V_T E_f}{X_s} = \frac{3 \times 2300 \times 2920}{1.1 \times \sqrt{3}} = 6105 \text{ KVA}$$

$$I_{F \text{ max}} = 10A$$

$$V_f = 200V$$

$$R_{\text{adj}} = 20 \rightarrow 200 \Omega$$

given: power limit of prime mover = 800 kW



to find intersection

Points, write equations.


$$x^2 + y^2 = (1000)^2$$

$$x^2 + (y + 4809)^2 = (6105)^2$$

$$x = 800$$

Lecture #6

• Synchronous Motors:




* stator is the same as in synchronous generator & induction motor. it will produce a rotating magnetic field which will interact with the rotating field from the rotor that is rotating with the same speed. & this will produce a Torque.

$$P = K \vec{B}_{net} \times \vec{B}_R$$

$$= K B_{net} B_R \sin(\delta)$$

equivalent ckt:




من الجهد المولد

$$E_m = V_T - I_s Z_s$$


$$E_m + I_s Z_s = V_T$$

Phasor diagram:


lagging P.F




unity P.F



leading P.F.



* neglecting R_a.



we can control E_m by the value of I_f ^{applied}

big $I_f \rightarrow$ big $E_m \rightarrow I$ (leading)


small $E_m \rightarrow I$ (lagging).

∴ the motor works as a variable reactance.

$$I_f \rightarrow E_m \rightarrow \phi$$

الفولتية المتبقية في المحرك

* Induction motor always has a lagging p.f.



$$P = \sqrt{3} V_L I_L \cos \theta$$

constants

∴ $(I_L \cos \theta)$ must stay constant.

$$\hookrightarrow (\cos \theta \downarrow) \rightarrow (I_L \uparrow) \rightarrow (P_{\text{Loss}} = I^2 R_{T.L.} \uparrow)$$

↓
زيادة الفقد

Power factor correction: we can achieve this by adding capacitors parallel to the induction motor, or by adding synchronous motor, which will work as a motor & as a variable capacitor simultaneously.

ex= 3φ, 400V, 10KVA, 50Hz, SM (synch. motor).

R_a negligible.


$$X_s = 2 \Omega$$

& Field current is adjusted to give 1 p.f.

1) find the full load current

$$I_{FL} = \frac{10000}{\sqrt{3} \times 400} = 14.43 \text{ A } / 0^\circ$$

$$E_m = \frac{400 \text{ V}}{\sqrt{3}} - 14.43 \times j2 = 231 - j28.8 = 232.7 / -7.1^\circ$$



2) field current is increased by 10%, keeping the same load.

$$E_{f2} = (1+0.1) E_{f1} = 232.7 \times 1.1 = 256 \text{ V}$$

$$P = \frac{3V_T E_m \sin \delta}{X_s} = \text{constant}$$


if E_m is increased by 10%, ∴ $\sin(\delta)$ must be decreased by 10%

$$\frac{\sin(\delta_1)}{\sin(\delta_2)} = 1.1 \Rightarrow \frac{E_{m2}}{E_{m1}} = \frac{\sin(-7.1)}{\sin(\delta_2)}$$

$$\delta_2 = -6.43^\circ$$

$$V_T - IjX_s = E_m$$

$$I = \frac{V_T - E_m}{jX_s} = \frac{231 - 256 \angle -6.45}{j2} = 18.53 \angle 39^\circ$$




3) field current is decreased 10% from (1).

$$E_{m3} = 0.9 E_{m1} = 0.9 \times 231 = 209.43$$


$$\frac{\sin(\delta_1)}{\sin(\delta_3)} = 0.9$$

$$\delta_3 = -7.89^\circ$$


$$I_3 = \frac{231 - 209 \angle -7.89^\circ}{j2} = 18.7 \angle -39.9^\circ$$



Lecture #7



↳ generator (+ve δ)



↳ motor (-ve δ)

example: 208V / 45KVA / 0.8 p.f leading / Δ-connected / 60Hz / $X_s = 2.5 \Omega$

$P_{F\&W} = 1.5 \text{ kW}$ / $P_{\text{core}} = 1 \text{ kW}$ / R negligible / $P = 15 \text{ hp}$ at 0.8 p.f leading
 ↳ friction & windage

1) $P_{\text{out}} = (15 \text{ hp} \times 746) = 11190 \text{ Watt}$

$P_{\text{IN}} = 11190 + 1500 + 1000 = 13690 \text{ Watt}$

$I = \frac{13690}{\sqrt{3} \times 208 \times 0.8} = 47.5 \text{ A}$

$I_{\phi} = \frac{47.5}{\sqrt{3}} = 27.4 / 37^{\circ} \leftarrow + \cos^{-1}(\text{p.f.})$


$E_A = 208 - 27.4(0.8 + j0.6)j2.5 = 255 \angle -12.4^{\circ} \text{ V}$

2) P was increased to 30 hp.

$P_2 = 30 \times 746 = 22380 \text{ Watt}$

$P_{\text{IN}} = 22380 + 1000 + 1500 = 24880 \text{ Watt}$

* field current was kept constant $\rightarrow \therefore E_m$ is constant




$$\frac{P_1}{P_2} = \frac{\sin(\delta_1)}{\sin(\delta_2)} = \frac{\sin(-12.4^\circ)}{\sin(\delta_2)}$$

$$\frac{13690}{24880} = \frac{\sin(-12.4)}{\sin(\delta_2)}$$

$$\delta_2 = -22.97^\circ$$

$$I_A = 208 - 255 \angle -22.97^\circ = 41.22 \angle 15.1^\circ \text{ A}$$



$$P.F. = \cos(15.2) = 0.965 \text{ leading}$$


3) keeping the same P while decreasing I_f by 10%.

$$\therefore E_{A3} = 0.9 \times 255 = 229.5 \text{ V}$$


$$\frac{P_1}{P_3} = 1 = \frac{E_1 \sin \delta_1}{E_3 \sin \delta_3}$$

$$0.9 = \frac{\sin(\delta_1)}{\sin(\delta_3)}$$

$$\delta_3 = -13.8^\circ$$






$$I_2 = \frac{208 - 229.5 \angle -13.8^\circ}{j2.5} = 22.69 \angle 15.2^\circ \text{ A}$$



$$T_3 > T_2 > T_1$$

V-curve



(since it's a synchronous motor, has a constant freq.)

Lecture #8

Power factor correction using synchronous motors:

ex: A factory has the following:

1. induction motor of 500kVA, 0.8 PF lagging.
 2. ~ ~ ~ 600hp, 0.85 PF lagging, 90% efficiency.
 3. lighting load, 100kVA, 1PF
- required to add 400hp load and correct PF to 0.96 lag. (efficiency 88%).

find the (KVA) of the synch. motor to be added

Load	P	Q	S	P.F	θ
1	400	300	500	0.8	36.8°
2	497	308	584.7	0.85	31.8°
3	100	0	100	1	0
4	339.1	-218.5	403.4	0.84	-32.79°
total	1336.1	389.5	1391.77	0.96	16.26°

$500 \times 0.8 = S_1 \sin(\theta)$
 $400 \text{hp} \times 0.746 = 298.4 \text{ kW}$
 $\frac{298.4}{0.88} = 339.1 \text{ kW}$
 $600 \text{hp} \times 0.746 = 447.6 \text{ kW}$
 $\frac{447.6}{0.9} = 497 \text{ kW}$
 $S_2 = \frac{P_2}{\text{PF}_2} = \frac{497}{0.85} = 584.7$
 $Q_2 = S_2 \sin \theta_2 = 308 \text{ kVAR}$
 $\left(\frac{\sum P_i}{\text{P.F.}_{\text{tot}}} \right) = \frac{1336.1}{0.96}$
 $Q_{\text{tot}} = 1391.77 \sin(16.26^\circ)$

* it's better (economically) to use a synch. motor instead of a capacitor with induction motor.



in the previous ex. if we wanted to have a unity PF.

$\text{PF}_{\text{tot}} = 1 \rightarrow Q_{\text{tot}} = -608 \quad \& \quad \text{P.F.}_4 = 0.487$
 $Q_{\text{tot}} = 0 \quad S_4 = 696.17$

Starting of SM:


1. By prime mover:

- (i) at no-load by IM (induction motor). (until it approaches the synch. speed).
- (ii) Pumping Station: one of the methods used to store electrical energy.



at (low load) period. water is pumped upward, so that it can be used at high load period to generate energy


2. by starting as IM:



if ① is closed \rightarrow SL \rightarrow induction motor
 when the motor approaches synch. speed switch the switch to ② & it will be a synch. motor.

Lecture #9

3. Amortisseur (Damper) winding:




a current will flow through these windings until the rotor approaches the synchronous speed (stator & rotor fluxes will rotate at the same speed). then current through these windings will become zero.

* when a load is added to the motor its speed will decrease, & a current will flow through the windings, accelerating the motor back to its synch. speed. when the load is removed the speed will increase but the damper windings will also drive the motor back to its synch. speed.

∴ damper windings have 2 purposes:

1. starting the synch. motor.
2. damping out any oscillation that might be caused by sudden & changes in the load.

5.4: 2300V, 1000hp, 0.8 p.f leading, 60Hz, 2poles, Y-connected,
 $X_s = 2.8 \Omega$, $R_a = 0.4 \Omega$, $P_{F&W} = 24 \text{ kW}$, $P_{\text{core}} = 18 \text{ kW}$
 $I_{F_{\text{max}}} = 10 \text{ A}$, $V_f = 200 \text{ V}$.



1) how much field current would be required to make the machine operate at unity power factor when supplying full load?

$$P_{\text{out}} = 1000 \text{ hp} \times 746 = 746000 \text{ Watt}$$

$$P_{\text{in}} = 746000 + 24000 + 18000 + 3I_{\text{st}}^2 \times 0.4 = \sqrt{3} \times 2300 I_{\text{st}}$$

$$I_{\text{st}} = 214 \text{ A}$$

← stator current

$$E_a = \frac{2300}{\sqrt{3}} - 214(0.4 + j2.8) = 1376 \angle -25.3^\circ$$

from the graph $\rightarrow I_f = 4.6 \text{ A}$

2) What's the motor's efficiency at full load & unity pf.?

$$\eta = \frac{746000}{746000 + 24000 + 18000 + 3 \times 214^2 \times 0.4} = 89.3\%$$

3) if the field current was increased by 5 percent, what would the new value of the armature current be? What would the new power factor be? how much reactive power is being consumed or supplied by the motor?

$$I_{F2} = 4.6 \times 1.05 = 4.83 \text{ A}$$

from graph

$$E_{a2} = 2450 \text{ (L-L)}$$

$$= \frac{2450}{\sqrt{3}} = 1414.5 \text{ V (L-N)}$$

$$\frac{E_{f1} \sin(\delta_1)}{E_{f2} \sin(\delta_2)} = 1 \quad \leftarrow \text{constant P}$$

$$\frac{1376 \times \sin(-24.3)}{1414.5} = \sin(\delta_2)$$

$$\delta_2 = -24.6^\circ$$

$$I_2 = \frac{2300}{\sqrt{3}} - \frac{1414.5 \angle -24.6^\circ}{0.4 + j2.8} = \boxed{214.5 \angle 3.5^\circ}$$

$$Q = \sqrt{3} \times 2300 \times 214.5 \times \sin(-3.5^\circ) = \boxed{-52.2 \text{ kVAR}} \quad (\text{capacitive})$$

4) What's the maximum torque this machine is theoretically capable of supplying at unity p.f.?

$$P = \frac{3 V_T E_f \sin \delta}{X_s} = \frac{3 \times \frac{2300}{\sqrt{3}} \times 1414.5 \times 1}{2.8}$$


$$T = \frac{P}{\omega} = \frac{P}{\frac{2\pi}{60} \times \frac{120 \times 60}{2}} = 5193 \text{ N.m}$$

synch. gen.

5.16 480V, 500kVA, 0.8 p.f lagging, Y, $X_{sg} = 0.4 \Omega$, SG is supplying a SM with, 480V, 80kW, 0.8 p.f leading Y-connected, $X_{sm} = 2 \Omega$

$V_T = 480V$, at unity p.f. & rated power.

1) calculate \vec{E}_a for both machines.






$$E_g - I \times 0.4 = \frac{480}{\sqrt{3}}$$

$$\Rightarrow E_g = 280 \angle 7.9^\circ$$

$$E_m + I \times j1.1 = \frac{480}{\sqrt{3}}$$

$$\Rightarrow E_m = 297 \angle -20.9^\circ$$

$$I = \frac{80000}{\sqrt{3} \times 480} = 96.2 \text{ A}$$



Lecture #10


ex cont. 2) if the flux of the motor is +10%, find V_ϕ new?

$$I_{AM} = I_{AG} = 96.2 \angle 0^\circ \text{ A} \quad \left. \begin{array}{l} \\ \end{array} \right\} \text{ in-phase (unity p.f.)}$$

$$V_\phi = \frac{480}{\sqrt{3}} = 277 \angle 0^\circ \text{ V}$$

$$E_{AG} = 280 \angle 7.9^\circ \text{ V}$$

$$E_{AM} = 297 \angle -20.9^\circ \text{ V} \xrightarrow{+10\%} 327 \text{ V}$$



$$\delta = \delta_g + \delta_m$$

$$I_m = I_g = \frac{E_{AG} - E_{AM}}{j(X_m + X_g)} \quad \text{--- ①}$$

$$P = \frac{3 E_{AM} E_{AG} \sin(\delta)}{(X_m + X_g)}$$

$$= \frac{3 \times 327 \times 280 \sin \delta}{1.1 + 0.4} = 80000$$

$$\delta = 29.9^\circ$$

from ①

$$I_m = I_g = \frac{280 - 327 \angle -29.9^\circ}{j1.5} = 95.7 \angle 5.7^\circ \text{ A}$$


$$V_\phi = E_{AG} \angle 0^\circ - j I_g X_g$$

$$= 280 \angle 0^\circ - j 95.7 \angle 5.7^\circ \times 0.4$$

$$= 286 \angle -7.6^\circ$$

take E_{AG} as a reference.

if V_ϕ is the reference



$$I'_m = 95.7 \angle 5.7 + 7.6 = 95.7 \angle 13.3^\circ \text{ A}$$

6.12 Y-connected SM, 21000 hp, 1200 r.p.m, 6600 V, 1 p.f

≈ 5.15

3φ, 1404 A, $T_{ext} = 5.2$, $V_{ext} = 125$, $X_s = 0.9$ p.u., $R_a = 0.02$ p.u.

(figure 5-21)

1) What's the rated input power of this motor?

$$S = \sqrt{3} \times 6600 \times 1404 = 16.05 \text{ MVA}$$

$$P = \boxed{16.05 \text{ MW}} \text{ (unity p.f.)}$$

$$S_{base} = 16.05 \text{ MVA}$$

$$V_{T,base} = 6600 \text{ V}$$

$$V_{\phi,base} = \frac{6600}{\sqrt{3}} = 3811 \text{ V}$$

$$I_{base} = 1404 \text{ A}$$

$$Z_{base} = \frac{3811}{1404} = 2.71 \Omega$$

2) What's the magnitude of E_A at rated conditions?

$$E_a = 1 - j(0.02 + j0.9) = 1.33 \angle -42.6^\circ \text{ p.u.}$$

$$= 1.33 \times 3811 = \boxed{5067} \angle -42.6^\circ \text{ V.}$$

3) if $P_{in} = 10 \text{ MW}$, what's the maximum reactive power the motor can simultaneously supply?

$$Q = \sqrt{16.05^2 - 10^2} = 12.6 \text{ MVAR}$$

$$10 \text{ M} = \frac{3 \times 3811 \times 5067 \sin \delta}{2.71 \times 0.9}$$

$$\delta = -24.9^\circ$$

$$I_{p.u.} = \frac{1 \angle 0^\circ - 1.33 \angle -24.9^\circ}{j0.9} = 0.663 \angle 20.2^\circ \text{ p.u.}$$


$$= 0.663 \times 1404 = 931 \angle 20.2^\circ \text{ A}$$

$$Q = 3 \times 3811 \times 931 \sin(20.2) = 3.68 \text{ MVAR}$$

$$\times \frac{3 E_A V_\phi}{X_s} = \frac{3 \times 5067 \times 3811}{2.7 \times 0.9} = 23.75 \quad \text{--- ①}$$

$$\times \frac{3 E_A^2}{X_s} = \frac{3 \times 5067^2}{2.7 \times 0.9} = 31.58 \quad \text{--- ②}$$


$$\text{②} - \text{①} = 7.83$$



$$T = \frac{P}{\omega} = \frac{P}{1200 \times \frac{2\pi}{100}}$$

lecture # 11

• Induction motor:



* its rotation speed < synchronous speed.

typical (standard) speeds:-

$$2900 \rightarrow \text{if } P=2 \quad \omega_{\text{sych}} = 3000 > 2900$$



$$1440 \rightarrow \text{if } P=4 \quad \omega_s = 1500 > 1440$$

$$970 \rightarrow \text{if } P=6 \quad \omega_s = 1000 > 970$$

* for $f=50\text{Hz}$

• Types of induction motor:

1. Squirrel cage.
2. Wound rotor (slip ring).



$$P = k \vec{B}_r \times \vec{B}_s$$

rotor's flux is at synchron. speed
while rotor's body is not.

$\omega_s =$ synchron. speed.

$\omega_m =$ mechanical speed.

$\omega_s - \omega_m =$ relative speed between
stator & rotor.

$$* S \equiv \text{Slip} = \frac{\omega_s - \omega_m}{\omega_s} = \frac{n_s - n_m}{n_s}$$

↑ [rad/s]
↑ [rpm]

ex:- a motor with 2 poles, 50 Hz, $n_s = 3000$ rpm, $n_m = 2900$ rpm

$$S = \frac{3000 - 2900}{3000} = 0.033$$


relative speed = $3000 - 2900 = 100$ → this speed will induce the current in the rotor
 $\therefore f_r = S f_{\text{stator}}$

$$f_2 = S f_1$$

$$f_2 = 50 \times 0.033 = 1.66 \text{ Hz}$$

Lecture # 12

Induction motor's exact equivalent CKT:-




"Transformerly equivalent of IM"

Stator = primary

air gap has higher reluctance
∴ ↓ Φ

due to hysteresis & eddy + we'll add to it mechanical losses (windage & friction) due to rotor's movement.



→ we need more current to generate high Φ. (than in transformer)


∴ X_m is smaller in IM. (due to air gap).

Since f₂ = sf₁

s ≈ 0.05, 0.04 at full speed f₂ << f₁

∴ in the rotor f ↓ → emf ↓

∴ we'll deal with rotor alone first:-



rotor's equ. CKT

* emf depends on freq.


$$E = 4.44 N \Phi(f)$$

$$E_2 = \underbrace{4.44 N \Phi(f_1 s)}_{E_{02}}$$

$$E_2 = s E_{02}$$

$$jX'_2 = \underbrace{j2\pi f_1 L s}_{X_2}$$


$$= jX_2 s$$



$$I_2 = \frac{S E_{02}}{R_2 + jX_2 S} = \frac{E_{02}}{\frac{R_2}{S} + jX_2}$$

$$I_2 = \frac{E_{02}}{\frac{R_2}{S} + jX_2}$$


So, we can modify the CKT as follows:-



(I_2)'s freq. will be considered = f_1


now plug this CKT in the full CKT. but with $\frac{R_2}{S}$ into

- 1) R_2
- 2) $R_2 \left(\frac{1-S}{S}\right)$




* do not forget to take turns ratio into consideration this CKT is referred to primary.

* Power dissipated in $R_2 \left(\frac{1-S}{S}\right) = P_{out}$ (of mech. load).




• Approximated equ. CKTs:-

1) IEEE recommended equ. CKT:



2) Equivalent CKT for circle diagram:-



* no-load current of IM $\approx 30\%$ of full load current!
while in transformer $\approx 1\%$!

Lecture #13

ex: 208 V, 10hp, 4p, 60 Hz, Y, S=0.05

$$n_s = \frac{120f}{p} = \frac{120 \times 60}{4} = 1800 \text{ rpm}$$

$$s = \frac{n_s - n_m}{n_s} \rightarrow n_m = n_s(1-s) = (1-0.05) \times 1800 = 1710 \text{ rpm}$$

$$f_2 = sf_1 = 0.05 \times 60 = 3 \text{ Hz}$$

$$n_{\text{relative}} = 1800 - 1710 = 90 \text{ rpm} \rightarrow \frac{90}{120} \times 4 = 3 \text{ Hz}$$

$$P = 10 \times 746 = 7460 \text{ Watt}$$

$$T = \frac{P}{\omega_m} = \frac{7460}{1710 \times \frac{2\pi}{60}} = 41.7 \text{ N.m}$$

ex2: 480 V, 60 Hz, 50hp, 3 ϕ , 60 A, 0.85 P.F lagging.

Primary losses \leftarrow $P_{scL} = 2 \text{ kW}$, $P_{stray} = 0$, $P_{rcL} = 700 \text{ W}$, $P_{f\&w} = 600 \text{ W}$, $P_{core} = 1800 \text{ Watt}$

Secondary losses.

$$P_{IN} = \sqrt{3} \times 480 \times 60 \times 0.85 = 42400 \text{ Watt}$$

$$P_{AG} = P_{IN} - P_{scL} - P_{core} = 42400 - 1800 - 2000 = 38.6 \text{ kW}$$


$$P_{conv} = P_{AG} - P_{rcL} = 37.9 \text{ kW} \equiv P_{mech.}$$

↑
converted to mechanical

$$P_{out} = 37.9 \text{ kW} - 600 \text{ W} = 37.3 \text{ kW} \equiv \frac{37.3}{746} = 50 \text{ hp}$$

$$\eta = \frac{P_{out}}{P_{IN}} = \frac{37.3}{42.4} = 88\%$$

* if $P_{stray} \neq 0$ we subtract it at the end from $P_{conv.}$



$$P_{AG} = 3 I_2^2 \left(\frac{R_2}{s} \right) \quad \text{--- (1)}$$

$$P_{RCL} = 3 I_2^2 R_2 \quad \text{--- (2)}$$

① / ② :

$$P_{RCL} = s P_{AG}$$

$$P_{conv} = P_{AG} - P_{RCL} = (1-s) P_{AG}$$

$$T_{dev} = \frac{P_{mech}}{\omega_{mech}}$$

$$P_{mech} \equiv P_{conv}$$

$$T = \frac{(1-s) P_{AG}}{\omega_m} = \frac{(1-s) P_{AG}}{(1-s) \omega_s}$$

$$\therefore \boxed{T_{dev} = \frac{P_{AG}}{\omega_s}}$$

Ex:- 460 V, 25 hp, 60 Hz, Y, 4 P, ← we don't use this

$$R_1 = 0.641 \Omega \quad R_2 = 0.332 \Omega$$

$$X_1 = 1.106 \Omega \quad X_2 = 0.464 \Omega$$

$$X_m = 26.3 \Omega \quad P_{rot} = 1100 \text{ Watt}$$


$$s = 2.2\%$$

1. Speed:

$$n_s = \frac{120 f}{P} = \frac{120 \times 60}{4} = 1800 \text{ rpm}$$

$$n_m = (1 - 0.022) \times 1800 = 1760 \text{ rpm}$$

2. Stator current at this speed:



$$Z_T = 0.641 + j1.106 + \frac{j26.3 \left(\frac{0.332}{0.022} + j4.64 \right)}{j26.3 + \frac{0.332}{0.022} + j0.464} = 14.05 / 33.68^\circ$$

$$I_1 = \frac{460}{\sqrt{3}} \frac{1}{14.05 / 33.68^\circ} = 19.71 / -33.6^\circ$$

$$P_{IN} = \sqrt{3} \times 460 \times 19.71 \cos(33.68) = 13636 \text{ W}$$

P.F

$$P_{scl} = 3I_1^2 R_1 = 3(19.71)^2 \times 0.641 = 747 \text{ W}$$

$$P_{IN} - P_{scl} = P_{AG}$$

$$\rightarrow P_{AG} = 13636 - 747 = 12889 \text{ W}$$

$$P_{PCL} = s P_{AG} = 0.022 \times 12889 = 283.56$$

$$P_{conv} = 12889 - 283.56 \approx 12606$$

$$P_{out} = P_{conv} - P_{Rot} = 12606 - 1100 = 11506 \text{ W}$$


$$\eta = \frac{11506}{13636} \times 100 = 84.4\%$$

Torque: $\rightarrow T_{developed}$
 $\searrow T_{out}$

$$T_{out} = \frac{P_{out}}{\omega_m} = \frac{11506}{\frac{2\pi \times 1760.4}{60}} = 62.4 \text{ N.m}$$

$$T_{dev} = \frac{P_{AG}}{\omega_s} = \frac{P_{conv}}{\omega_m} = \frac{12889}{\frac{2\pi \times 1800}{60}} = 68.4 \text{ N.m}$$

$$= \frac{12606}{\frac{2\pi \times 1760.4}{60}}$$



* Reversing the direction of rotation is done by reversing any two phases.

Lecture # 14

from prev. ex.:

$$460V, \quad R_1 = 0.641 \Omega, \quad R_2 = 0.332 \Omega$$

$$X_1 = 1.106 \Omega, \quad X_2 = 0.464 \Omega$$

$$X_m = 26.3 \Omega$$

1. Find the starting torque? ($s=1$)

$$I_{st} = \frac{460}{\sqrt{3}} \frac{1}{0.641 + j1.106 + \frac{j26.3(0.332 + j0.464)}{j26.3 + 0.332 + j0.464}} = 145 \angle -58.8^\circ$$

(starting current)

$$I_1 \text{ at } s=0.022 = 14.05 \text{ (prev. lect.)}$$

$$\frac{I_{st}}{I_1} = \frac{145}{14.05} = 10.3 \text{ times!}$$

$$P_{IN} = \sqrt{3} \times 460 \times 145 \cos(58.8) = 59846 \text{ Watt}$$

$$P_{scl} = 3 \times 145^2 \times 0.641 = 40431$$

$$P_{AG} = 59846 - 40431 = 19414 \text{ Watt}$$

$$= P_{PCL} \text{ since } \omega_m = 0 \rightarrow \therefore P_{conv} = 0.$$

$$T = \frac{19414}{1800 \times \frac{2\pi}{60}} = 103 \text{ N.m}$$



$$\frac{T_{st}}{T_{FL}} = \frac{103}{68.4} = 1.51$$

$I_{R_{rotor}}?$

$$P_{PCL} = 19414 = 3I_r^2 \times 0.332$$

$$\rightarrow I_r = \sqrt{\frac{19414}{3 \times 0.332}} = 139.61 \text{ A (referred to Primary)}$$

* end of 1st material.



$$Z_{TH} = \frac{jX_m (R_1 + jX_1)}{jX_m + R_1 + jX_1} \approx R_{TH} + jX_{TH} \quad \text{--- ①}$$

$$V_{TH} = V_1 \frac{jX_m}{jX_m + R_1 + jX_1} \approx V_1 \frac{X_m}{X_m + X_1} \quad (\text{neglecting } R_1)$$

$$= K_{TH} V_1$$

$$\left(K_{TH} = \frac{X_m}{X_m + X_1} < 1 \right) \approx 0.96$$

from ①

$$R_{TH} \approx K_{TH}^2 R_1$$

$$X_{TH} \approx X_1$$


"بس rotor ال مقوم لا يساوي Thev. ال"

** Power in $V_{TH} \neq P_{IN}$

$$I_2 = \frac{V_{TH}}{(R_{TH} + \frac{R_2}{s}) + j(X_{TH} + X_2)}$$

$$P_{AG} = 3I_2^2 \frac{R_2}{s} = \frac{3V_{TH}^2 R_2/s}{(R_{TH} + \frac{R_2}{s})^2 + (X_{TH} + X_2)^2}$$

$$T_{dev} = \frac{P_{AG}}{\omega_s} = \frac{3V_{TH}^2 R_2/s}{\omega_s [(R_{TH} + \frac{R_2}{s})^2 + (X_{TH} + X_2)^2]}$$



max T ? from the derivative $\frac{d T_{dev}}{ds} = 0$


or T is max when $\frac{R_2}{s} = \sqrt{R_{TH}^2 + (X_{TH} + X_2)^2}$ ← max. Power transfer when $Z_L = Z_{TH}$.

$$s_{Tmax} = \frac{R_2}{\sqrt{R_{TH}^2 + (X_{TH} + X_2)^2}}$$

$$T_{max} = \frac{3V_{TH}^2}{2\omega_s [R_{TH} + \sqrt{R_{TH}^2 + (X_{TH} + X_2)^2}]}$$

* notice that $s_{Tmax} \propto R_2$


While T_{max} doesn't depend on R_2 (constant for different values of R_2)




$$R_2''' > R_2'' > R_2' > R_2$$

* we control R_2 by an external resistor added in series with

$$R_2 \rightarrow R_2' = R_2 + R_{ext}$$



→ we can add R_{ext} at starting to give max. torque then short CRT it after a while



Machines II

NoteBook

Dr. Mohammad Z. Khader

By: Hasan Shannak


بأفكارنا نبدع

4th & 5th Weeks

7.14

440 V, 50 Hz, 2P
 Y 75 kW
 $R_1 = 0.075$ $R_2 = 0.065$
 $X_1 = 0.17 = X_2$
 $X_m = 7.2$

$P_{FW} = 1 \text{ kW}$ $P_{mis} = 150 \text{ W (stray)}$
 $P_{core} = 1.1 \text{ kW}$ $S = 0.04$



$$Z_{eq} = 0.075 + j0.17 + \frac{j7.2 \left(\frac{0.065}{0.04} + j0.17 \right)}{j7.2 \left(\frac{0.065}{0.04} + j0.17 \right)} = 1.68 \angle 18.3$$

$$I_1 = \frac{440/\sqrt{3}}{1.68 \angle 18.3} = 149.4 \angle -18.3$$

$$P_{in} = \sqrt{3} \times 440 \times 149.4 \cos(18.3) = 108 \text{ kW}$$

$$P_{scL} = 3 \times 149.4^2 \times 0.075 = 5 \text{ kW}$$

$$P_{AG} = 108 - 5 = 103 \text{ kW}$$

$$P_{conv} = (1 - S) P_{AG} = (1 - 0.04) \times 103 = 98.88 \text{ kW}$$

$$P_{out} = 98.88 - 1 - 0.15 - 1.1 = 96.6 \text{ kW}$$

$$y = \frac{96.5}{108} = 89.47\%$$

(2)

$$P_{RCL} = s P_{AG} = 0.04 \times 103 = 4.12 \text{ kW}$$

$$P.F = \cos \theta = \cos 18.5 = 0.94699$$

$$K_{TH} = \frac{7.2}{7.2 + 0.17} = 0.98$$

$$V_{TH} = \frac{440}{\sqrt{3}} \times 0.98 = 248.95 \text{ 'phase'}$$

$$R_{TH} = 0.98^2 \times 0.075 = 0.072 \Omega$$

$$X_{TH} = X_1 = 0.17 \Omega$$

$$s_{I_{max}} = \frac{R_2}{\sqrt{R_{TH}^2 + (X_{TH} + X_2)^2}} = 0.189$$

$$n_s = \frac{120}{2} \times 50 = 3000$$

$$n_m = (1 - 0.189) \times 3000 = 2473 \text{ rpm}$$

$$T_{max} = \frac{3 V_{TH}^2}{2 \omega_s (R_{TH} + \sqrt{R_{TH}^2 + (X_{TH} + X_2)^2})}$$

$$= \frac{3 \times 440^2}{2 \times 3000 \times \frac{2\pi}{60} [0.072 + \sqrt{0.072^2 + (0.17 + 0.77)^2}]}$$



$$= 734 \text{ N.m}$$

what's the value of R_{ext} to get maximum Torque

$$\frac{s_{max1}}{s_{max2}} = \frac{0.189}{1} = \frac{R_2}{R_2 + R_{ext}} = \frac{0.065}{0.065 + R_{ext}} \Rightarrow R_{ext} = 0.28 \Omega$$

Find R_{ext} to make max torque occurs at 1500 rpm $s=0.5$

$$\frac{0.189}{0.5} = \frac{R_2}{R_2 + R_{ext}} \Rightarrow R_{ext} = 0.4 \Omega$$



$$I_{st} = \frac{248}{0.072 + j0.17 + 0.065 + j0.17}$$

$$= 676.6 \text{ A}$$

$$P_{AG} = 3 \times 676.6^2 \times \frac{0.065}{1} = 89.256 \text{ Kw}$$

$$T_{ST} = \frac{P_{AG}}{\omega_s} = 284 \text{ Nm}$$

For $R_{ext} = 0.11$

$$I_{st} = \frac{248}{0.072 + j0.17 + 0.065 + 0.11 + j0.17} = 540.1 \text{ A}$$


s (slip) $s=0.5$

$$T_{3ST} = \frac{3 \times 540.1^2 \times (0.065 + 0.11)}{3000 \times \frac{2\pi}{60}} = 582 \text{ Nm}$$

If we increase 20% freq \Rightarrow 60 Hz

\rightarrow Current decreases 20%, Impedance decreases 20%

Torque decreases 40%








Circle Diagram :


14-7-2014 ①

* Locus diagram:


• $f(z) = \frac{1}{z}$ Inversion = Y "Admittance"
↳ Impedance.



$$\text{slope} = \frac{R}{L} \text{ or } \frac{L}{R}$$



what happens for Y





$$\vec{y} = \frac{1}{X} = \frac{1}{|X|} \angle -\theta$$

$$= \frac{1}{p e^{j\theta}} = \frac{1}{p} e^{-j\theta}$$



$$|y| = \frac{1}{|X|}$$

$$\angle y = -\angle X$$



* The inverse of a straight line parallel to the x-axis is a circle with center on the y-axis




* The inverse of a straight line parallel to the y-axis is a circle with center on the x-axis





* the inverse of the straight line ~~passing~~ passing through the origin is a straight line passing through the origin







* straight line not passing through the origin is a circle passing through the origin.





* circle not passing through the origin, is circle passing through the origin isn't necessarily a same



⇒ inverse of a center isn't a center
 ⇒ " " a semi circular is n't ^{always} necessarily a semi circular



note $Y = G + jB$
 $\frac{1}{1}$
 $B \rightarrow +ve$ for capacitor




$bc = \sqrt{0.5^2 - 0.25^2} = 0.433$

$Z_{Tot} = \frac{1}{2} \pm 0.433$

$= \cancel{0.066} 0.066$
or 0.933

Pure resistive, For unity P.F. $r = \sqrt{1^2 + 0.25^2} = 1.03$

Y_{total} :




$\frac{1}{r} = \frac{1}{1.03} = 0.97$

$$mg = \frac{1}{2}$$

$$m_0 = \sqrt{\frac{1}{2}^2 + \frac{1}{4}^2} = 0.559$$

$$\frac{og}{b} = 0.559$$



$$\tan \theta = \frac{1}{2}$$



$$\theta = 26.57$$

$$\frac{1}{0.559} = 16.95$$

maximum
Y
or max
I
or min Z

$$P = s/c$$

$$X_c = 0$$



ال Z لقبيل الاضافة

$$\theta = \frac{1/4}{1/2} = \frac{1}{2}$$

$$\theta = 30^\circ$$

$$UV = \frac{1}{2} \cos 30 = 0.433$$

$$sV = 0.5 - 0.433 = 0.066$$

$$\tan \alpha = \frac{1/4}{0.066} = 3.75$$

$$\alpha = 75.8$$

$$Y_c = 3.75$$


$$X_c = \frac{1}{3.75} \Omega$$






check

$$\frac{1}{1+j3.75} + j\frac{1}{4} =$$

$$R+jX$$


$$X=0$$







① Find the value of the variable element resulting in total maximum Power factor

② Find the power in this case assuming $V_{in} = 10V$





PAPER ELECTRICAL ENGINEERING




$VY_{Tot} = I_{Tot}$

$V^2 Y_{Tot} = VA$



current origin) کے لیے کہیں کہیں
 Power --- اور // // //
 سہرے کو $R_2 \left(\frac{1-s}{s} \right)$ سے $s=1$



$\cos \theta = P.F.$

Tangent // Torque Line

Max torque happens when max PM "Air Gap"

PB \Rightarrow Input Power

NB \Rightarrow Power at Rc

MN \Rightarrow R_1

LM \Rightarrow R_2

PL $\Rightarrow \frac{R_2 (1-s)}{s}$ out put power


PM \Rightarrow P_{Airgap}

OB \Rightarrow Q

~~PR~~ $P_{RCL} = s P_{AG}$

$$s = \frac{P_{RCL}}{P_{AG}} = \frac{LM}{PM}$$

$$\eta = \frac{PL}{PB} \times 100\%$$



miniman P.F @ S=1

3.73 kW 200 V 50 Hz

4P 3φ

No load test 200V, I_L = 5A, P_{in} = 350

Blocked Rotor test V = 100V
I = 26A
P = 1200

• $\cos \theta_0 = \frac{350}{200 \times 5 \times \sqrt{3}} = 0.202$ 350 W → $\frac{350}{692} = 0.5$ cm

$\theta_0 = 78.3^\circ$

$\frac{5}{2} \rightarrow 2.5$

V_{BR} = 200 V

I = 26 * $\frac{200}{100}$ = 52 A

P = 1700 * $(\frac{200}{100})^2$ = 6800 W

Scale:


current: 1 cm = 2 A

Power: 1 cm = $\sqrt{3} \times 2 \times 200 = 692$ W

$\cos \theta_{BR} = \frac{6800}{\sqrt{3} \times 52 \times 200} = 0.377$

DBR = 67°

لو قسنا نقطة باخر النقطه
slip
Full load
 $\frac{3730}{692} = 5.4$ cm



(3)
 $\frac{T_{max}}{T_{FL}} = \frac{P_{AG}}{P_{out}} = \frac{6920}{3730}$

P.F. = $\frac{PB}{Po} = \cos \theta_p = 0.848$
I_{FL} = $\frac{P}{V} = 7.6 \times 2 = 15.2$ A

(2)
T_{max} = $\frac{6920}{1500 \times \frac{27}{60}} = 44$ Nm
TR = 10 cm
P_{AG} = 10 * 692 = 6920 W

starting Torque

(2)

$$4.8 - 0.5 = 4.3$$

$$P_{sc} G = \frac{4.3}{2} = 4.65 \text{ cm}$$

$$P_{AG} \text{ at starting} = 4.65 \times 692 \\ = 3217 \text{ W}$$

$$T_{st} = \frac{3217}{1500 \times \frac{2\pi}{60}} = 20.5 \text{ Nm}$$

$$\frac{T_{st}}{T_{FL}} = \frac{20.5}{\dots}$$

$$P_M = 5.6 \text{ cm} - P_{AG}$$

$$P_{AG} \times 692 = 3875$$

$$T_{FL} = \frac{3875}{1500 \times \frac{2\pi}{60}} = 24.7$$

$$s = \frac{LM}{PM} = \frac{0.2}{5.6} = 0.0357$$

$$\eta_{FL} = \frac{5.4}{6.33} = \frac{PL}{PB} = 85.7\%$$

15 hp, 208V

③

code letter F


3 ϕ

locked
rotor kVA


code letter F \Rightarrow 5.6 /

$$\begin{aligned} \text{locked rotor kVA} &= 15 \times 5.6 = 84 \text{ kVA} \\ &= 15 \times 5 = 75 \text{ kVA} \end{aligned}$$

$$I = \frac{84000}{\sqrt{3} \times 208} = 233 \text{ A}$$






Date: / /



Squirrel cage torque speed variation


في حالة زيادة سرعة المحرك (motor) لا يوجد طريقة لتغيير المقاومة



Slots
Al bar
aluminum
of Cu bar

Subject _____
Date _____


low freq
↳ I is distributed equally.



← low R_2

↳ at running.


Skin effect
(skin depth δ)



← high R_2


↳ at starting

∴ X_2 & R_2 are functions of s



Subject: _____

Date: _____



Speed (low best relatively)


Shape of Slot

A

B

C

D



~ 50%

~ 40%

~ 30%

~ 20%

$\frac{T_{st}}{T_{FL}}$

Starting torque

$\frac{T_{st}}{T_{FL}}$

1.5 to 1.75

2 to 2.5

2.75 to 3

~ Char. of flux pole in dia

High starting torque

$\frac{T_{st}}{I_{FL}}$

5 to 8

4.5 to 5

3.5 to 5

3 to 8

$\frac{T_{st}}{I_{FL}}$

High starting current

$\frac{P_{out}}{P_{in}}$

2.25

2.3

1.9 to 2.25


2.75

Subject


Date: / /

	<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>
Full S	2-5%	3-6%	4-8%	7-15%
usage	general purpose: Pump, fan, etc.		compressor	high speed
			compressor	low efficiency
			needs high starting P	high acceleration

double cage



Assume $\frac{R_2}{s} \ll X_2$



ex: $R_2 = 5 + j1$ upper cage
 $R_2 = 1 + j5$ lower cage

v_e induced emf in rotor.

① at $s=1$

$$E_1 = \frac{V}{s + j} = 0.2V$$

$$E_2 = \frac{V}{1 + j5} = 0.2V$$

Subject _____

Date: / /

Page: _____

$$P_1 = \frac{3 \times 6i^2 \times 5}{W_1} = \frac{3}{W_1} \left(\frac{3}{10} \right)^2$$

$$= 0.27$$

$$P_2 = 0.04 \text{ K}$$

back A B C

$$\frac{P_1}{P_2} = \frac{0.27}{0.04} = \frac{27}{4} = 6.75$$


at $S = 0.05$ $i = \frac{V}{\frac{5}{0.05} + j1} = 0.01V$

$$i_2 = \frac{V}{\frac{1}{0.05} + j1}$$

$$P_1 = K(0.01)^2 \times \frac{5}{0.05} = 0.01 \text{ K}$$

$$P_2 = K(0.05)^2 \times \frac{1}{0.05} = 0.05 \text{ K}$$

$$\frac{P_1}{P_2} = \frac{1}{5}$$




Handwritten notes and scribbles at the bottom right of the page, including some illegible text and a signature.

New Trends in Induction Motors Constructions

21-7-2014 ①

1. More copper in the stator.
2. Increasing the length to ~~need~~ reduce magnetic saturation & core loss
3. more steel to reduce heat + Fan
4. Using special steel of high grade of low hysteresis Loss
5. thin gauge steel to reduce eddy current loss
استعمال حديد رقيق
6. Machining surface to reduce stray losses.
تنعيم السطح لتقليل الخسائر الضالة




Nominal efficiency:

NEMA "Notinal Electrical Manufacturing Association"

Nominal η <small>المكتوب على case</small>	Guaranteed minimum η <small>كم لازم تكون القطع</small>
95%	94.1%
94.1%	93%
91%	89.5%
84%	85%
81.5%	77% 78.5%
80%	66% 77%
70%	66%
50.5%	46%

Starting Code Letter



Nominal Code Letter

locked rotor KVA
hp


A	0 → 3.15
B	3.15 → 3.55
C	3.55 → 4
F	5 → 5.6
K	8 → 9
L	9 → 10
P	12.5 → 14
V	22.4 → 40

Starting of I.M.

1) wound rotor by "rotor resistance variation"


2) Squire cage: by auto transformer series (resistance or reactance) $I \propto V$
 $I \propto V$
Y Δ


قلد ۱ ۷ قلد ۱ I بتقل ۱ مع بعن



motor terminal

- a) close 1 & 3
- b) open 1 & 3 close








* Typical motor starter across the line



* $I_{FL} <= I_{fuse}$ (Arabic text: * إذا كان I على حد I_{FL} في fuse يجب أن يكون $I_{FL} <= I_{fuse}$)




let the com make the contact on





3-step resistor starter IM

Usually running as Δ



Speed control of IM

~~Squirrel cage~~
Wound rotor



squirrel
Cage

Voltage decreases by 10%
T_{org} " by 20%

مع تغییر فرکانس

Squirrel
Cage
motor

اسکال






POWER ELECTRICAL ENGINEERING

Speed control of IM:


1. by changing numbers of poles

$$n_s = \frac{120 f}{P}$$



$f = 50$



3 speeds
 $\frac{P}{4}$
6
8




series
Parallel





Derating:



إعادة تحديد
Rated voltage




general purpose
pumps



high starting torque






fan




لما قلت السرعة
زيد ال torque

change freq by pulse




Parameters Measurements of IM:-



• DC resistance

$$\frac{V_{dc}}{I_{dc}} = 2R_1$$




$$\frac{V_{dc}}{I_{dc}} = \frac{2R_1 R_1}{3R_1} = \frac{2}{3} R_1$$


No Load:

P_{NL}, I_{NL}, V_{NL}
 ↓
 rated voltage

3φ



Two wattmeters method



• R_{NL}

$$\frac{R_2}{s} = \infty$$

$$j(X_1 + X_m)$$

$$3 I_{NL}^2 R_{NL} = P_{NL}, \quad 3 I_{NL}^2 R_1 = P_{\text{stator copper loss}}$$

$$P_{\text{mech}} + P_{\text{core}} = P_{NL} - P_{\text{sc}} = \text{rotational copper loss}$$

$$Z_{NL} = \frac{V_{NL} / \sqrt{3}}{I_{NL}}$$

$$X_{NL} = \sqrt{Z_{NL}^2 - R_{NL}^2}$$

23-7

⑤


R_{NL} = مقاومة ضالفة

لعمل $egav$ جديدة ckt

تسهل العمل

POWER ELECTRICAL ENGINEERING UNITY

* Blocked (locked) Rotor Test:-



• $V_{BR} = V_{Blocked\ rotor}$, I_{BR} , P_{BR}

Core losses jX_m / لا تأخذ في الحسبان

$Z_{BR} = \frac{V_{BR}/\sqrt{3}}{I_{BR}}$, $P_{BR} = I_{BR}^2 \underbrace{(R_1 + R_2)}_{R_{BR}}$, $s=1$ starting

$R_2 = R_{BR} - R_1$

$X_{BR} = \sqrt{Z_{BR}^2 - R_{BR}^2} = X_1 - X_2$

• Wound Rotor:

	$0.5 X_{BR}$	X_2	0.5
Class A	$0.5 X_{BR}$		0.5
Class B	$0.4 X_{BR}$		0.6
Class C	0.3		0.7
Class D	0.5		0.5

At reduced frequency
 $X_m + X_1 = \text{from no load}$
 $\Rightarrow X_m$

7.18

NLT: 208V 22A 1200W 60Hz no load test

BRT: 24.6V 64.5 2200W 15Hz Blocked rotor test

DC test: 13.5V 64A

class BY

R1 = 13.5 / (2 * 64) = 0.105 Ω

ZNL = 208 / (sqrt(3) * 22) = 5.455 Ω

RNL = 2200 / (3 * (22)^2) = 0.826

XNL = X1 + Xm = sqrt(ZNL^2 - RNL^2) = 5.39 = Xm + X1

PBR = 2200 / (3 * (64.5)^2) = 0.176

R2 = PBR - R1 = 0.071 Ω

X'BR = sqrt(ZBR^2 - RBR^2), ZBR = 24.6 / (sqrt(3) * 64.5) = 0.22 Ω

X'BR = sqrt(0.22^2 - 0.176^2) = 0.132

XBR = 0.132 * 60 / 15 = 0.528 Ω "class B"

X1 = 0.4 * 0.528 = 0.2112 Ω

X2 = 0.6 * 0.528 = 0.317 Ω

Xm = 5.39 - 0.2112 => Xm = 5.18 Ω

RNL - R1 = 0.826 - 0.105 = 0.721

PRC = (22)^2 * (0.721) * 3 = 1046.9 W

7.19

460 V, 4 P, 50 hp, 60 Hz

(3)

$$R_1 = 0.33 \Omega, X_m = \cancel{30} \Omega \rightarrow 30 \Omega$$

$$X_1 = 0.42 \Omega = X_2$$


$$R_2 = ?, S = 0.038$$

$$\bullet V_{Th} = V_1 \times \frac{X_m}{X_1 + X_m} = \frac{460}{\sqrt{3}} \times \frac{30}{0.42 + 30} = 262 \text{ V}$$

$$\bullet R_{Th} = R_1 k_{Th}^2 = R_1 \times \left(\frac{X_m}{X_1 + X_m} \right)^2 = 0.321$$

$$X_{Th} = X_1 = 0.42$$

$$\bullet T_{der} = \frac{P_{out}}{\omega_{gm}} = \frac{50 \times 746}{\left(\frac{2\pi}{60} \times \frac{120(60)}{4} \right) (1-S)} = 205.7 \text{ N.m}$$



$$\bullet T = \frac{P_{AG}}{\omega_s} = \frac{3 I^2 \frac{R_2}{s}}{\frac{2\pi}{60} \times \frac{120(60)}{4}}$$

$$\bullet I = \frac{V_{Th}}{\left(R_{Th} + \frac{R_2}{s} \right) + j(X_{Th} + X_2)}$$


$$\bullet |I| = \frac{V_{Th}}{\sqrt{\left(R_{Th} + \frac{R_2}{s} \right)^2 + (X_{Th} + X_2)^2}} = \frac{262}{\sqrt{\left(0.321 + \frac{R_2}{s} \right)^2 + (0.42 + 0.42)^2}}$$


$$T = \frac{3 \left(\frac{R_2}{s} \right) \left(\frac{(262)^2}{\left(0.321 + \frac{R_2}{s} \right)^2 + (0.42 + 0.42)^2} \right)}{\frac{2\pi}{60} \times \frac{120(60)}{4}}$$

$$\left(\frac{R_2}{5}\right)^2 - 4.669\left(\frac{R_2}{5}\right) + 0.702 = 0$$

$$\frac{R_2}{5} = 0.156 \quad \text{or} \quad 4.13$$

$$R_2 = 0.0059 \quad , \quad R_2 = 0.172$$





Machines II

NoteBook

Dr. Mohammad Z. Khader

By: Rania Daraghmeh


بأفكارنا نبدع

6th week


→ Single Phase induction motors:-

a. Universal motor →

AC ← AC is like BL
DC ← DC is like BL



Its structure is basically the same as DC motor.



$\tau = k \phi I_a$
Series Inductance

AC is like BL DC is like BL







Core must be laminated to minimize eddy current. (not solid)

(Eddy current depends on thickness, it & hysteresis are the sources of heat)

$\sqrt{2} V_{rms} = V_{peak}$


⇒ Saturation causes more losses.






Diode for AC








⇒ Cross field theory:-



* B_r is \perp to I_r .





B_s & $B_r \approx 80^\circ$



→ Single phase IM:

(We mean by this the AC motor).





توليد حقل مغناطيسي متذبذب


*pulsating mmf

The single phase motor can't move itself (the starting can't be accomplished alone)

Double Revolving Theorem.



Equivalent to a 1φ motor.



Notice that the rotor magnetic field rotates from maximum to 0 to minimum due to the phase shift ($\approx 90^\circ$ here), which leads the net result is rotating magnetic field, but the rotor & stator components are stationary.


→ Split phase induction motor :-








The problem is at starting I don't have starting torque. To generate one I place 2 windings \perp to each other.

$$\tan \theta_a = \frac{X_a}{R_a} ; \text{ [small ratio of } \frac{X_a}{R_a} \text{ by having a large } R_a \text{]} \\ \text{(i.e. small gauge = small } \theta \text{)}$$

$$\tan \theta_m = \frac{X_m}{R_m} \Rightarrow \text{Regular...}$$




* I open the switch a few seconds after the motor is started, because the auxiliary is not needed anymore.



← what happens in the above circuit




→ Capacitor Start Motor:




$$\tan \theta_m = \frac{X_m}{R_m} \Rightarrow \text{Big}$$

$$\tan \theta_a \Rightarrow \text{Small}$$


The phase shift between the auxiliary & main is 20 or 30° maximum, but if I add a capacitor I can make it 90°



Used for motors that require a high starting torque.




⇒ Phasor Diagram of this



* Capacitor Run motor:-


I remove the switch in this case.

* Capacitor start capacitor run



Shaded pole motor:-

I make this winding short circuit when I wrap a wire around it





so the flux is concentrated on the other poles.

Toys for kids & few watts applications


if the hp is more than 3hp it becomes 3Ø


→ 2nd Exam Till here.

Equivalent Circuit:-




Equivalent CKT of 3Ø





← Equivalent Circuit of 1ϕ.

P_{AG} $P_{conv.} = P_{AG} - P_{REL}$



↳ $Z_F = \frac{jX_m \left(\frac{R_2}{s} + jX_2 \right)}{jX_m + \frac{R_2}{s} + jX_2} = R_F + jX_F$

$Z_{backward} = \frac{jX_m \left(\frac{R_2}{2-s} + jX_2 \right)}{jX_m + \frac{R_2}{2-s} + jX_2} = R_B + jX_B$

$I_1 = \frac{V_1}{R_1 + jX_1 + [R_F + jX_F] + [R_B + jX_B] \cdot 0.5}$

$P_{AG} = I_1^2 (R_F - R_B)$

$T_{conv.} = \frac{P_{AG}}{\omega_s}$ $P_{scL} = I_1^2 R_1$

$$P_{ACL} = P_{ACLF} + P_{ACLB}$$

$$= 5P_{AGF} + 5P_{AGB}$$

$$\approx 5(P_{AG})$$

$$\therefore P_{AGF} = I_1^2 R_F \rightarrow P_{AGB} = I_1^2 R_B$$


→ Example :-

10.1) 120 V $\frac{1}{3}$ hp split-phase

$$R_1 = 1.8 \Omega \quad X_1 = 2.4 \Omega \quad X_m = 60 \Omega$$

$$R_2 = 2.5 \Omega \quad X_2 = 2.4 \Omega \quad s = 0.05 \quad P_{Bot} = 51 \text{ W}$$

→ Sol.



$$Z_F = \frac{j60 \left(\frac{2.5}{0.05} + j2.4 \right)}{j60 + \frac{2.5}{0.05} + j2.4} = 28.15 + j24.87 \Omega$$

$$Z_B = \frac{j60 \left(\frac{2.5}{1.95} + j2.4 \right)}{j60 + \frac{2.5}{1.95} + j2.4} = 1.185 + j2.332 \Omega$$

$$I = \frac{120}{1.8 + j2.4 + \frac{1}{2} [28.15 + j24.87 + 1.185 + j2.332]} = 5.23 \angle -44.2^\circ$$

$$P_{in} = 120 \times 5.23 \cos 44.2^\circ = 450 \text{ W}$$

$$P_{AGF} = 5.23^2 \times 2.15 \times 0.5 = 386 \text{ W}$$

$$P_{AGB} = 5.23^2 \times 1.185 \times 0.5 = 16.2 \text{ W}$$

$$P_{AG} = 386 - 16.2 = 370 \text{ W}$$

$$P_{convB} = (1 - 0.05) \times 16.2 = 15.4 \text{ W}; P_{convF} = (1 - 0.05) \times 386 = 367 \text{ W}$$

$$P_{conv} = 367 - 15.4 = 352 \text{ W}$$

$$P_{out} = 352 - 51 = 301 \text{ W}; P_{in} = 120 \times 5.23 \cos 44.2 = 450 \text{ W}$$

$$\eta = \frac{301}{450} \times 100 = 56.9\%$$

$$T_{out} = \frac{301}{1710 \times \frac{2\pi}{60}} = 1.68 \text{ Nm}$$

$$T_{conv} = \frac{370}{1800 \times \frac{2\pi}{60}} = 1.97 \text{ Nm}$$

$$n_s = 1800 \text{ rpm}$$

$$n_m = (1 - 5) n_s = 1710$$

⇒ Problem 10.3 (Important):

$$n_m = 400 \quad n_m = 1800 \text{ given previously}$$

$$s = \frac{1800 - 400}{1800}$$

$$= 0.778$$

$$Z_f = \frac{j60 \left(\frac{2.5}{0.778} + j2.4 \right)}{j60 + \frac{2.5}{0.778} + j2.4} = 2.96 + j24.6 \Omega$$

$$Z_b = \frac{j60 \left(\frac{2.5}{(2 - 0.778)} + j2.4 \right)}{j60 + \frac{2.5}{2 - 0.778} + j2.4} = 1.9 + j2.37 \Omega$$

$$I = \frac{120}{1.8 + j2.4 + 0.5(2.96 + j2.46 + j2.37)} = 18.37 \angle -48.7^\circ$$

$$P_{AGF} = 18.73^2 \times 2.96 \times 0.5 = 519.2 \text{ W}$$

$$P_{AGB} = 18.73^2 \times 1.9 \times 0.5 = 331.5 \text{ W}$$

$$P_{\text{conv. F}} = 519.2 \times (1 - 0.778) = 115.2 \text{ W}$$

$$P_{\text{conv. B}} = 331.5 \times (1 - 0.778) = 73.6 \text{ W}$$

$$P_{\text{conv}} = 115.2 - 73.6 = 41.6 \text{ W}$$

∴ It will stop because $41.6 < 51$

$$P_{\text{conv}} < P_{\text{rot}}$$

$$T_{\text{ind}} = \frac{519.2 - 331.5}{1800 \times \frac{2\pi}{60}} = 1 \text{ Nm}$$

↳ For problem 10.1 previously, suppose the voltage is reduced to 100V. Calculate the η & torque.

$$I_1 = 5.23 \times \frac{100}{120} = 4.356 \text{ A}$$

$$P_{\text{in}} = 450 \times \left(\frac{100}{120}\right)^2 = 312 \text{ W}$$

$$P_{\text{conv}} = 352 \times \left(\frac{100}{120}\right)^2 = 244.4 \text{ W}$$

$$P_{\text{out}} = 244.4 - 51 = 193 \text{ W}$$

$$\eta = \frac{193}{312} = 62\%$$

$$T_{\text{conv.}} = 1.97 \times \left(\frac{100}{120}\right)^2 = 1.3 \text{ Nm}$$

$$T_{\text{out}} = \frac{193}{1710 \times \frac{2\pi}{60}} = 1 \text{ Nm}$$

$$= 1 \text{ Nm}$$

Problem 10-7)

For the vacuum cleaner, I use a universal motor
Refrigerator, I use capacitor start motor or/capacitor
run motor (موتور کپاسیتر).

Air Conditioning, also capacitor start motor

Easy speed control,

Fan, split motor,

