

MACHINES II

DR.SADEQ HAMED

BY:FARAH ALLAN



Lecture [1] :- AC Machines

Two major types :-

- Induction machines \Rightarrow Pure AC, mainly used as motors

- Synchronous machines \Rightarrow combination of AC (stator or armature) and DC (rotor), mainly used as generators (alternators).

* cheapest machine between all types of machines is Induction.

* \rightarrow these machines are mainly 3-phase; machines above 5 kW \rightarrow 3-ph

Both types :- have same principle of operation. Basic concept of these machines is the Rotating field.

$$\text{electric speed} = 2\pi f \quad \text{mech speed}$$

$$* W_e = P * W_m$$


\downarrow
pole pairs

\Downarrow
have fixed speed and amplitudes created in the Stator (armature).

\rightarrow Yoke: ferromagnetic cylinder with at least 6 slots.

Mech speed = Inversely proportional to the number of Poles.


* * these directions on the slots are at $t=0$



* * each 2 slots belong to a certain phase.

- A: A' → phase A
- B: B' → phase B
- C: C' → phase C

* these coils are excited 3-phase balanced currents from a 3-phase power supply.



$$i_A = I_m \sin(\omega t)$$

$$i_B = I_m \sin(\omega t - 120)$$

$$i_C = I_m \sin(\omega t - 240)$$

$t=0 \rightarrow \omega t = 0 \text{ rad}$

$$* i_A = 0 \rightarrow \text{MMF} = N_{ph} * i_A = 0$$

$$* i_B = I_m \sin(0 - 120) = -\frac{\sqrt{3}}{2} I_m$$


$$F_B = N_{ph} * i_B = N_{ph} * -\frac{\sqrt{3}}{2} I_m = -\frac{\sqrt{3}}{2} F_{max}$$

$$* i_C = I_m \sin(0 - 240) = \frac{\sqrt{3}}{2} I_m$$

$$F_C = \frac{\sqrt{3}}{2} I_m * N_{ph} = \frac{\sqrt{3}}{2} F_{max}$$

$$* F_{total} = F_A + F_B + F_C = \sqrt{3} * \frac{\sqrt{3}}{2} F_{max}$$

$$= \frac{3}{2} F_{max}$$




\Rightarrow total MMF = $\frac{3}{2} F_{max}$ (Max MMF / Phase)

* this arrangement will create a flux that is $\frac{3}{2} \phi$ (ph) and two poles are created at certain phase in the armature.

Lecture [23]

H.W solution





at $\omega t = 90$

$i_1 = I_m \sin(\omega t) = I_m \sin(90) = I_m$

$i_2 = I_m \sin(\omega t - 120) = I_m \sin(90 - 120) = -\frac{I_m}{2}$

$i_3 = I_m \sin(\omega t - 240) = I_m \sin(90 - 240) = -\frac{I_m}{2}$





$$\Rightarrow F_{\text{total}} = \overline{F_A} + \overline{F_B} + \overline{F_C}$$

$$= f_m + \frac{f_m}{2} = \frac{3}{2} f_m$$

*** Results** :- By having such an arrangement, an MMF is created.

This field has

a) constant amplitude, that is $\frac{3}{2} f_m$, where f_m is maximum MMF per phase.

This is true irrespective of the No. of windings or even poles.

b) The MMF created is rotating at a speed, that is N_s (RPM), usually referred to as the "Synchronous Speed"

السرعة المتوافقة

$$\text{Angular speed: } \omega_s = \frac{2\pi N_s}{60} \text{ rad/Sec}$$

* N_s is a function of :

① the supply frequency. (f)

② the No. of poles.

$$N_s = \frac{60f}{P}$$

, P is the No. of pole pairs

* to control the speed of the Rotating field N_s , supply frequency should be varies up or down.


The No. of poles is usually fixed for a certain machine ($P=1$ or 2 or $3 \dots$)

$$N_s = \frac{60}{1} f \quad \text{or} \quad \frac{60}{2} f, \quad \frac{60}{3} f \dots$$

$f = 50 \text{ Hz}$ \downarrow 3000 RPM \downarrow 1500 RPM \downarrow 1000 RPM \rightarrow European design.



$f = 60 \text{ Hz}$ 3600 1800 1200 RPM $\dots \rightarrow$ US design

G) By the shown winding arrangement, two poles can be created. Higher No. of poles can be achieved through winding arrangement, below is an example of a 4 pole machine.



* when the electric angle is 90° , the field MMF moves $\frac{90}{P} = \frac{90}{2} = 45^\circ$


* To change the direction of rotation of a 3-ph motor, the supply phase sequence is to be changed.



⇒ on the machine we change the wire between i_B & i_C .

try: at $\omega t = 60$

at $\omega t = 90$



ABC ⊕
~~into~~ ACB ⊖

Lecture [3]

$$\omega_s = \frac{2\pi N_s}{60} = \frac{2\pi f}{60} = \frac{\omega_e}{P}$$

$$\omega_e = P\omega_s$$

$$\omega_e \gg \omega_s$$

** AC Rotating machines:-

AC Rotating Mach


Induction

* mainly used as motors.


Synchronous

* mainly used as generators.

(Power stations)



* Stator of both types is similar.



Created EMF

$$E_{ph} = 4.44 k_w * f * \phi * N_{ph}$$

↳ winding factor $\approx 0.93 \rightarrow 0.97$

$$k_w \approx 1$$

** Rotor of Induction machine

I.M


squirrel cage Rotor

wound Rotor

99%


1%

• Squirrel-cage Rotor.




End Ring makes short circuit around the slots to have a closed loop.


• Wound Rotor



** Mech interfacing between rotating Rotor and stationary resistance box.



• Resistance box



* Wound Rotor cost is almost 3 that of squirrel cage.

** Lecture [4]

IM (Asynchronous Machine) $[N_m \leq N_s]$

1) Squirrel-cage.
- simple & cheap.

2) Wound Rotor
- expensive (2 → 3) cost of Sq.
- excellent for starting purposes. (reduce starting current and increase starting torque).

** Synchronous Machines:- $[N_m = N_s]$

Stator: Same as that of IM

Rotor: Two types

1) Salient-poles. (توربينات)

2) Round Rotor. relating Low-Speed Machine. // driven by hydrolic turbines.


- Salient pole :-

a) Permanent poles
($\phi = \text{constant}$)

b) electric poles.

- electric coil is wound and excited by DC current to create magnet field ϕ .

(ϕ is variable by varying I_f (field current))




2) Round Rotor

/cylindrical Rotor.

(turbo)


Field windings



* two-poles machine.

high speed : $N_s = \frac{60 f}{P}$

$P \rightarrow P = 1 \text{ or } 2$



**** Synchronous machines**


Two types:

- a) Salient pole.
- b) cylindrical (Round-Rotor).

* Major types in terms of the input power:

1 Hydraulic → driven by hydraulic turbine.
hydrolic turbine driven SG

- relatively low speed
 (large No of poles) 6, 8, 10, ...
- large Rotor Diameter
 power ∝ diameter, length
- Small length.
- vertically shaft



2 Thermal (turbo) Turbines.

→ high speed (3000 or 1500)
 $P = (1, 2)$

- Small Diameter
- large length
- Horizontal shaft.

** Excitation systems:-

I_f → field current is required to be controllable.

a) to control Internal EMF = E_a or E_f

$$E_f = 4.44 * k_w * N_p * f * \phi$$

↑
speed related.

$$f = \frac{P N_m}{60}$$

constant

$$\phi = K_f I_f$$

$$\Rightarrow E_f = K \cdot I_f$$

b) to control the generated reactive power Q .

$$S = P \oplus jQ$$

by field current I_f ,
and hence the power factor.

\ominus → leading PF → for ~~generators~~ Motor

\oplus → lagging PF → generators

